

Digital

Midas PRO SERIES



Service Support Bulletin

Issue	When Midas Pro series consoles have a router or switch connected to the Ethernet control port without the Remote Control Server being "active", the system can act unpredictably over a larger time window
Action	Always ensure that the router/switch is powered off or disconnected if the Remote Control Server is not active

985-40000-00871 Rev.A
2019-07-18

Music Tribe accepts no liability for any loss which may be suffered by any person who relies either wholly or in part upon any description, photograph, or statement contained herein. Technical specifications, appearances and other information are subject to change without notice. All trademarks are the property of their respective owners. Midas, Klark Teknik, Lab Gruppen, Lake, Tannoy, Turbosound, TC Electronic, TC Helicon, Behringer, Bugera, Auratone and Coolaudio are trademarks or registered trademarks of Music Tribe Global Brands Ltd. © Music Tribe Global Brands Ltd. 2019 All rights reserved.

Confidential, for internal use only. Not to be reproduced.

MIDAS